
Final exam (01H30)

Question (02 points):

1. Give the main starting methods of induction motors.

Exercise 01 (08 points):

The nameplate of a separately excited DC motor shows the following information:

$$U = 240 \text{ V}, I = 35 \text{ A}, P_u = 7 \text{ kW}, n = 800 \text{ rpm}$$

A. Calculate (at rated load):

- 1- The motor efficiency, given that the inductor copper losses are 150 W .
- 2- The armature copper losses, given that the armature resistance is 0.5Ω .
- 3- The electromagnetic power and the collective losses.
- 4- The electromagnetic torque, the useful torque, and the torque due to constant losses.

B. The motor operates at constant torque. The armature still absorbs $I = 35 \text{ A}$. To control the speed, we modify the voltage U .

- 1- Name an electronic device that allows the speed control.
- 2- The new voltage U takes the value $U' = 110 \text{ V}$. Calculate the new e.m.f. (E') and the corresponding rotation speed (n').

Exercise 02 (10 points):

The characteristics of a three-phase alternator are as follows:

- Star-connected stator windings at the frequency of 50 Hz .
- No-load characteristic: $E = 152 \cdot I_e$
- Resistance between two phases of the armature $R = 1 \Omega$.
- Synchronous reactance $X_S = 1.75 \Omega$.

1. Find the synchronous impedance of the machine Z_S .
2. The alternator supplies a balanced three-phase inductive load with a power factor of 0.8 . The RMS line voltage at the armature terminals $U = 5.5 \text{ kV}$. The RMS line current $I = 577 \text{ A}$.
 - 2.1 What is the intensity of the excitation current I_e ?
 - 2.2 Calculate the copper losses in the armature p_{js} .
 - 2.3 A no-load test gave the total no-load losses equal to 80 kW . What is the efficiency of the alternator?

جامعة سعيدة د. مولاي الطاهر



اللقب و الاسم

تاريخ و مكان الميلاد

الإمتحان

رقم المرشح

القسم

الكلية

لا يكتب المرشح
في هذا المربع

رقم

المادة: In depth electrc mach

Question:

* Main starting methods of induction machines

Soft starter - star - delta - Limmer

Cherostat - reduced load

Exercise 01: 08

$$U = 240V \quad I = 35A \quad P_u = 7kW$$

$$n = 800 \text{ rpm}$$

A.1. Motor efficiency: $\eta = \frac{P_u}{P_A}$

$$P_A = UI + I^2 R_e$$

$$P_{fe} = \frac{1}{2} R_e I_e^2$$

$$= \frac{1}{2} (R_e I_e) I_e$$

$$= \frac{1}{2} I_e R_e$$

$$= \frac{1}{2} \cdot 150 \cdot 35$$

$$= 8400 + 150$$

$$P_A = 8550 \text{ W}$$

$$\eta = \frac{7000}{8550} = 81,87\%$$

لا يكتب المرشح
في هذا المربع

رقم

قيمة الورقة

على

إمضاء المصححين

1

A.2. Armature copper losses:

$$P_{sR} = R I^2 = 0,5 \cdot 35^2 = \boxed{612,5 \text{ W}}$$


(1)

A.3. Electromagnetic power

$$P_{EM} = E I$$

$$E = U - R I$$

$$= 240 - (0,5 \cdot 35) = 222,5 \text{ V} \quad U = E + R I$$



$$P_{EM} = 222,5 \cdot 35 \Rightarrow P_{EM} = \boxed{7787,5 \text{ W}}$$

(0,5)

- Collective losses:

$$P_c = P_m + P_s = P_{EM} - P_{sR} = 7787,5 - 612,5$$

$$\boxed{P_c = 7175 \text{ W}}$$

(0,5)

A.4. Electromagnetic torque:

$$T_{em} = \frac{P_{EM}}{\Omega} = \frac{7787,5}{800 \cdot \frac{2\pi}{60}} = \boxed{92,95 \text{ Nm}}$$

(1)

* لا يكتب أي شيء هنا *

Useful torque :

$$T_u = \frac{P_u}{\omega} = \frac{7000}{800 \cdot \frac{2\pi}{60}} = 83,55 \text{ N.m}$$

(1)

Torque due to constant losses :

$$T_p = \frac{P_c}{\omega} = \frac{787,5}{800 \cdot \frac{2\pi}{60}} = 9,40 \text{ N.m}$$

(1)

$$= T_{em} - T_u$$

B.1. In order to reduce the voltage

we use a buck chopper.

(1)

$$B.2. \quad U' = 110 \text{ V} \quad I = 35 \text{ A}$$

$$E' = U' - RI = 110 - (0,5 \cdot 35)$$

$$E' = 92,5 \text{ V}$$

$$E = k n'$$

(0,5)

$$k = \frac{E}{n} \Rightarrow n' = \frac{E'}{E} n$$

$$n' = \frac{92,5}{222,5} \cdot 800 = 333 \text{ rpm}$$

(0,5)

Exercice 01: $E = 152 \text{ V}$ (10)

$$R = 1 \Omega \Rightarrow R_1 = 0.5 \Omega$$


$$X_s = 1.75 \Omega$$

1. Synchronous impedance Z_s :

$$Z_s = \sqrt{R_1^2 + X_s^2}$$

$$= \sqrt{0.5^2 + 1.75^2}$$

$$Z_s = 1.82 \Omega$$



2. $V = 55 \text{ kV}$ $I = 577 \text{ A}$ $\cos \phi = 0.8$

$$\phi = 36.86^\circ$$


$$\underline{E} = \underline{V} + \underline{R_1 I} + \underline{X_s I}$$

$$= \frac{5500}{\sqrt{3}} + 0.5 \cdot 577 \cos(36.86^\circ) \underline{I}$$


$$+ j 0.5 \cdot 577 \sin(36.86^\circ) + 1.75 \cdot 577 \cos(90^\circ - 36.86^\circ)$$

$$+ j 1.75 \cdot 577 \sin(90^\circ - 36.86^\circ)$$

$$\underline{E} = 3175.426 + 230.829 - j 173.060 + 605.710 + j 807.904$$



جامعة سعيدة د. مولاي الطاهر



اللقب و الاسم

تاريخ و مكان الميلاد

الامتحان

رقم المرشح

القسم

الكلية

لا يكتب المرشح
في هذا المربع

رقم

Suite

المادة

$$\underline{E} = 4011,965 + j634,844$$

$$\underline{E} = 4061,88 \angle 8,99^\circ \quad V$$

$$I_e = \frac{E}{152} \Rightarrow I_e = 26,722 \quad A$$

2. Copper losses in the armature:

$$P_{gs} = 3 \cdot R_a \cdot I^2 = 3 \cdot 0,5 \cdot 577^2$$

$$P_{gs} = 499393,5 \quad W$$

3. Efficiency: $P_g = 80.000 \quad W$

$$P_{ue} = \sqrt{3} \cdot U \cdot I \cdot \cos \varphi = 4397330,590 \quad W$$

$$\eta = \frac{P_{ue}}{P_{ue} + P_{gs}} = 88,35 \%$$

لا يكتب المرشح
في هذا المربع

رقم

قيمة الورقة

على

إمضاء المصححين